## NORTH SCARLE PARISH COUNCIL

## ANNUAL ASBESTOS REPORT NORTH SCARLE HERITAGE ROOM / POST OFFICE

Visual inspection at the above of areas having potential ACM together with an inspection of vegetation on the exterior walls that may impact on relevant areas.

DATE	POSITION	CONDITION REPORT	ACTION
28 02 2025	Front gable cement fillets	Intact and undisturbed.	Monitor Annually.
28 02 2025	Rear gable cement fillets	Intact and undisturbed.	Monitor Annually.
28 02 2025	Left soffit possible cement fillet	Intact and undisturbed.	Monitor Annually.
28 02 2025	Right soffit possible cement fillet	Intact and undisturbed.	Monitor Annually.
28 02 2025	Exterior Walls	No ACM noted.	None.

Signature Date 28 02 2025